

34 Central Avenue Hauppauge, New York 11788-4734 Phone: (800) 645-1056 Fax: (631) 231-6059

Tuesday, June 24, 2003

195 Sandalwood Parkway W. Brampton, Ontario L7A 1J6 Phone: (905) 846-4545 Fax: (905) 846-9611

TECHNICAL BULLETIN

MISSING OPERATION – ACTION REQUIRED

- SUBJECT: CAR DOOR OPEN SIGNAL
- EQUIPMENT: PEELLE CAR DOORS WITH PLC (2742) CONTROLLER SERIES
- DESCRIPTION: PEELLE HAS DISCOVERED THAT THE CAR DOOR OPEN RELAY (GOF) MAY BE MISSING FROM OUR CONTROLLER ASSEMBLY. THE GOF CONTACT MAY BE REQUIRED FOR PROPER OPERATION OF THE DOORS WHEN IN FIRE SERVICE MODE DEPENDING ON THE ELEVATOR TO PEELLE CONTROLLER INTERFACE. IF THE GOF RELAY IS MISSING, THE SAME SIGNAL CAN BE ACHIEVED WITH A MECHANICAL SWITCH ACTUATED BY THE CAR DOOR PANEL.

*JOBS SHIPPED AFTER 6/20/2003 HAS BEEN CORRECTED.

- ACTION: CHECK PEELLE CONTROLLER ASSEMBLY FOR THE GOF RELAY AND THE CAR DOOR RAIL FOR PEELLE 09686 LIMIT SWITCH. IF THE RELAY AND THE 09686 LIMIT SWITCH ARE MISSING, CONTACT PEELLE TO OBTAIN 09686 LIMIT SWITCH AND MOUNTING BRACKET. INSTALL PER ATTACHED DRAWING AND WIRE BACK TO CONTROLLER THROUGH X15 AND X16.
- PEELLE HELP: SHOULD YOU REQUIRE TECHNICAL ASSISTANCE, PLEASE CALL JOSE VILCHEZ AT (905) 846-4545 x214 OR STEVE MULLEN AT x215.

